



HLA980-Counterflashing



HLA415-Sidewall Channel



HLA234-Utility Cleat with Return

		ATAS INTERNATIONAL, INC Allentown PA 610-395-8445 Mesa AZ 480-558-7210	
		Colonial Seam Sidewall Detail	
DWG. NO.	DR	DATE	
01	KRK	5/11/2016	
REV. NO.	APP	DATE	
12/11/2020			
DESCRIPTION OF REVISION	BY	SCALE	
Updated Sidewall Trim SKU	KRK	B	X:X

Note: * denotes color side.